WATER SUPPLY WELL REPORT

MULT 1241 (as required by ORS 537.765)
Instructions for completing this report are on the last page of this form.

Received Date 12/31/1929

Start Card #

Well ID # L

(1) OWNER Well Number 2	(9) LOCATION OF HOLE By legal description
Name FRANKLIN STENZEL	County Multnomah Latitude Longitude
STENZEL, PAUL; STENZEL, FRANZ R	Township 1.00 N Range 2.00 E Subdivision
Street 14015 NE GLISAN ST	Tax lot -99999 Lot Block
City PORTLAND State OR Zip 97230	Section 36 SE 1/4 NW 1/4
2) TYPE OF WORK	Street Address of Well (or nearest address)
New Alter (Recondition) Alter (Repair)	
Deepening Abandonment	MAP with location indentified must be attached
3) DRILL METHOD	(10) STATIC WATER LEVEL
Rotary Air Rotary Mud Cable Auger	Ft. below land surface. Date 12/31/1929
Other DRILLED	Artesian Pressure 0 lb/sq. in. Date
4) PROPOSED USE	(44) WATER READING TONES
Domestic Community Industria Irrigatio Injection	(11) WATER BEARING ZONES Depth at which water was first found ft.
Livestoc Thermal Other	Deptir at which water was first found it.
(5) BORE HOLE CONSTRUCTION	
pecial Standards Depth of completed well 260 ft.	
xplosives Used	
How as seal placed: Method Other	(12) WELL LOG
Backfill placed from ft. TO ft. Material	Ground * NOT ORIGINAL
Filter pack from	Ground * NOT ORIGINAL
(6) CASING/LINER	
	form created USING
	Form created using available data.
	Not able to locate
	original log.
7) PERFORATION/SCREENS	
Perforation Method	
Screens Type Material	Information Services
	l l
	3/30/98
	Date started 12/31/1929 Completed 2/31/1929
8) WELL TESTS (Minimum testing time is 1 hour)	(unbonded) Water Well Constructor Certification:
· ·	I certify that the work I performed on the construction, alteration, or abandonmen this well is in compliance with Oregon well construction standards. Materials used
	information reported above are true to the best knowledge and belief.
	WWC Number
Temperature of water °F/C Depth artesian flow found ft.	Signed By
Was water analysis done?	(bonded) Water Well Constructor Certification:
By Whom?	I accept responsibility for the construction, alteration, or abandonment work perfo on this well during the construction dates reported above. All work performed during
Did any strata contain water not suitable for intended use? Too Little Salty	this is in compliance with Oregon well construction standards. This report is true the tof my knowledge and belief
Mudd Odor Colored Other	best of my knowledge and belief. WWC Number 9999
Depth of strata ft.	Signed By