



CITY OF PORTLAND CATHEDRAL PARK IRRIGATION WELL
9/27/99 Step Test Performance - SWL 22' Below Ground Surface



CITY OF PORTLAND AND CATHEDRAL PARK IRRIGATION WELL

9/27/99 Recovery from Step Test



RECEIVED

DEC 07 1999

Schneider Drilling Co.

RECEIVED

JAN 06 2000

WATER RESOURCES DEPT.
SALEM, OREGON

Cathedral test data & graphs rec graph