

STATE OF OREGON

OCT 18 2002

WATER SUPPLY WELL REPORT

(as required by ORS 537.765)

WATER RESOURCES DEPT.

SALEM, OREGON

Instructions for completing this report are on the last page of this form.

WELL I.D. #1

START CARD # 149076

(1) LAND OWNER

Name Port of portland/Trammel crow

Well Number

Address 8930 S.W. Gemi DrCity Beaverton Ore State Zip 97008(2) TYPE OF WORK Dewatering☐ New Well ☐ Deepening ☐ Alteration (repair/recondition) ☐ Abandonment

(3) DRILL METHOD:

☐ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger☐ Other water jet

(4) PROPOSED USE:

☐ Domestic ☐ Community ☐ Industrial ☐ Irrigation☐ Thermal ☐ Injection ☐ Livestock ☐ Other dewatering

(5) BORE HOLE CONSTRUCTION:

Special Construction approval ☐ Yes ☒ No Depth of Completed Well 19 ft.Explosives used ☐ Yes ☐ No Type Amount

HOLE

SEAL

Diameter From To Material From To Sacks or pounds

see # 12How was seal placed: ☒ Method ☐ A ☐ B ☐ C ☐ D ☐ E☐ Other Backfill placed from ft. to ft. Material Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

Diameter From To Gauge Steel Plastic Welded Threaded

Casing: ☐ ☐ ☐ ☐☐ ☐ ☐ ☐☐ ☐ ☐ ☐☐ ☐ ☐ ☐☐ ☐ ☐ ☐☐ ☐ ☐ ☐Drive Shoe used ☐ Inside ☐ Outside ☐ NoneFinal location of shoe(s)

(7) PERFORATIONS/SCREENS:

☐ Perforations Method ☐ Screens Type Material

From To Slot size Number Diameter Tele/pipe size Casing Liner

☐ ☐☐ ☐☐ ☐☐ ☐

(8) WELL TESTS: Minimum testing time is 1 hour

☐ Pump ☐ Bailer ☐ Air ☐ Flowing ☐ Artesian

Yield gal/min Drawdown Drill stem at Time

1 hr.

Temperature of water Depth Artesian Flow Found Was a water analysis done? ☐ Yes By whom Did any strata contain water not suitable for intended use? ☐ Too little☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other Depth of strata:

(9) LOCATION OF WELL by legal description:

County Multnomah Latitude Longitude Township 2, n. N or S Range 1, W E or W. WM.Section 23 S.E. 1/4 S.E. 1/4Tax Lot 900 Lot Block Subdivision Street Address of Well (or nearest address) Port, Access

(10) STATIC WATER LEVEL:

2 ft. below land surface.Date 5-22-02Artesian pressure lb. per square inchDate

(11) WATER BEARING ZONES:

Depth at which water was first found 2 ft.

From	To	Estimated Flow Rate	SWL

(12) WELL LOG:

Ground Elevation

Material	From	To	SWL
Columbia river sand			
med. grey	0	19	2
24 inch casing water jetted to			
19 Ft. plastic casing installed 8'			
1" above grd 19' perforated			
5" = 18.36. 4x4			
24" casing pulled. well pumped			
for approx 5 days 15-20 gpm			
Well decommissioned 9-17-02			
8" casing pulled & gravel removed			
as much as possible with backhoe.			
filled back with original			
material & compacted.			

Date started 5-22-02 Completed 9-17-02

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

WWC Number Signed Date

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 1337Signed David Kaufman Date 10-16-02