

STATE OF OREGON
WATER SUPPLY WELL REPORT

(as required by ORS 537.765)

WELL I.D. # L 87876

START CARD # 188026

Instructions for completing this report are on the last page of this form.

(1) LAND OWNER
Name City of Portland Well Number _____
Address 3500 N. Victory Blvd.
City Portland State OR Zip 97217

(2) TYPE OF WORK New Well
 Deepening Alteration (repair/recondition) Abandonment Conversion

(3) DRILL METHOD
 Rotary Air Rotary Mud Cable Auger Cable Mud
 Other _____

(4) PROPOSED USE
 Domestic Community Industrial Irrigation
 Thermal Injection Livestock Other _____

(5) BORE HOLE CONSTRUCTION Special Construction: Yes No
Depth of Completed Well 124.6 ft.
Explosives used: Yes No Type _____ Amount _____

Diameter	BORE HOLE		Material	SEAL		Sacks or Pounds
	From	To		From	To	
22"	0	18	Cement	0	18	46 sacks

How was seal placed: Method A B C D E

Other _____
Backfill placed from _____ ft. to _____ ft. Material _____
Gravel placed from _____ ft. to _____ ft. Size of gravel _____

Diameter	From		Gauge	Steel	Plastic	Welded	Threaded
	From	To					
Casing: 14"	+1	0	.250	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Liner: N/A				<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Drive Shoe used Inside Outside None

Final location of shoe(s) _____

(7) PERFORATIONS/SCREENS
 Perforations Method N/A
 Screens Type _____ Material _____

From	To	Slot Size	Number	Diameter	Tele/pipe size	Casing	Liner
						<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>

(8) WELL TESTS: Minimum testing time is 1 hour
 Pump Bailer Air Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
N/A			

Temperature of water N/A Depth Artesian Flow Found _____

Was a water analysis done? Yes By whom _____

Did any strata contain water not suitable for intended use? Too little

Salty Muddy Odor Colored Other _____

Depth of strata: _____

(9) LOCATION OF WELL (legal description)
County Multnomah
Tax Lot 400 Lot _____
Township 1 N Range 1 E WM
Section 4 SW 1/4 NW 1/4

Lat _____° _____' _____" or _____ (degrees or decimal)
Long _____° _____' _____" or _____ (degrees or decimal)

Street Address of Well (or nearest address) Heron Lakes Golf Course
3500 N. Victory Blvd. Portland, OR 97217

(10) STATIC WATER LEVEL
12 ft. below land surface. Date 10-16-06
_____ ft. below land surface. Date _____
Artesian pressure _____ lb. per square inch Date _____

(11) WATER BEARING ZONES
Depth at which water was first found N/A

From	To	Estimated Flow Rate	SWL
N/A			

(12) WELL LOG Ground Elevation _____

Material	From	To	SWL
This old well did not have a surface seal. W.R.D. required the city to install a surface seal around the casing & extend the casing 12" above ground surface. No work or inspection was performed on the interior of the well.			

Westerberg Drilling, Inc.
36728 S. Kropf Rd.
Molalla, OR 97038

Date Started 10-12-06 Completed 10-13-06

(unbonded) Water Well Constructor Certification
I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

WWC Number _____ Date _____

Signed _____

(bonded) Water Well Constructor Certification
I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 888 Date 11-14-06

Signed Stevens N. Studer

RECEIVED

NOV 17 2006
WATER RESOURCES DEPT
SALEM, OREGON