#112

POLK 278

RECEIVED
JAN 18 1991
WATER RESOURCES DEPT.
SALEM, OREGON

G-3668

7S/4W/34 dd

STATE OF OREGON
WATER WELL REPORT
(as required by ORS 537.765)

(START CARD) # 27999

(1) OWNER: Well Number: —

Name Rickreall Water District
Address PO Box 41
City Rickreall State OR Zip 97371

(2) TYPE OF WORK:
☐ New Well ☐ Deepen ☑ Recondition ☐ Abandon

(3) DRILL METHOD
☑ Rotary Air ☐ Rotary Mud ☐ Cable
☐ Other

(4) PROPOSED USE:
☐ Domestic ☑ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval Yes ☐ No ☑ Depth of Completed Well 87 ft.
Explosives used Yes ☐ No ☑ Type — Amount —

HOLE Diameter	From	To	SEAL Material	From	To	Amount sacks or pounds
18"	0	20	Cement	0	20	13 sacks
12"	20	87	Original			

How was seal placed: Method ☐ A ☐ B ☑ C ☐ D ☐ E
☐ Other —
Backfill placed from — ft. to — ft. Material —
Gravel placed from — ft. to — ft. Size of gravel —

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	12"	+1	78	.250	☑	☐	☑	☐
	ORIGINAL				☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:					☐	☐	☐	☐
					☐	☐	☐	☐

Final location of shoe(s) —

(7) PERFORATIONS/SCREENS:
☐ Perforations Method
☐ Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour
☐ Pump ☐ Bailer ☑ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
100	40	85	1 hr.

Temperature of water 55 Depth Artesian Flow Found —
Was a water analysis done? ☐ Yes By whom —
Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other —
Depth of strata: —

(9) LOCATION OF WELL by legal description:
County Polk Latitude — Longitude —
Township 7S N or S. Range 4W E or W. WM.
Section 34 SE ¼ SE ¼
Tax Lot — Lot — Block — Subdivision —
Street Address of Well (or nearest address) Popular Ln. off of Independance Hwy.

(10) STATIC WATER LEVEL:
43 ft. below land surface. Date 12-14-90
Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:
Depth at which water was first found

From	To	Estimated Flow Rate	SWL

(12) WELL LOG: Ground elevation —

Material	From	To	SWL
Claystone-slough	78	87	
Reconstructed surface seal			
on existing well, cleaned out			
lower bore hole to 87' T.D.			

Date started 12-14-90 Completed 12-21-90

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.
WWC Number 1454
Signed for Jon McElwain Date

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. all work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.
WWC Number 723
Signed Date

ORIGINAL & FIRST COPY - WATER RESOURCES DEPARTMENT SECOND COPY - CONSTRUCTOR THIRD COPY - CUSTOMER 9809C 3/88