

POLK 53161

WATER WELL REPORT STATE OF OREGON

State Well No.

State Permit No.

File Original and
First Copy with the
STATE ENGINEER,
EM. OREGON

(1) OWNER:

Name Pacific Power & Light Co.
Address Independence, Oregon

(2) LOCATION OF WELL:

County Polk Owner's number, if any— 15 old Well
S 1/4 NE 1/4 Section 28 T. 3S R. 4 W.M.

Bearing and distance from section or subdivision corner

(3) TYPE OF WORK (check):

New Well Deepening Reconditioning Abandon
If abandonment, describe material and procedure in Item 11.

(4) PROPOSED USE (check):

Domestic Industrial Municipal
Irrigation Test Well Other

(5) TYPE OF WELL:

Rotary Driven
Cable Jetted
Dug Bored

(6) CASING INSTALLED:

Threaded Welded
12" Diam. from casing installed from Gage 5/16"
" Diam. from 13" above ground to Gage
" Diam. from depth of 59 feet to Gage

(7) PERFORATIONS:

Perforated? Yes No
Type of perforator used Mills Knife
SIZE of perforations 3/8 in. by 2 1/2 in.
perforations from ft. to ft.
102 perforations from 34 ft. to 58 ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

(8) SCREENS:

Well screen installed Yes No
Manufacturer's Name
Type Model No.
Diam. Slot size Set from ft. to ft.
Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:

Was well gravel packed? Yes No Size of gravel:
Gravel placed from ft. to ft.
Was a surface seal provided? Yes No To what depth? 18 ft.
Material used in seal—
Did any strata contain unusable water? Yes No
Type of water? Depth of strata
Method of sealing strata off

(10) WATER LEVELS:

Static level 20 ft. below land surface Date 6-9-61
Artesian pressure lbs. per square inch Date

Log Accepted by:
[Signed] Date, 19.....
(Owner)

(11) WELL TESTS:

Drawdown is amount water level is lowered below static level
Was a pump test made? Yes No If yes, by whom? Art Clinton
Yield: 1034 gal./min. with 14 ft. drawdown after 18 hrs.
" 300 " " 9 " 2 "
" 600 " " 3 " 2 "
" 400 " " " " "
Ballor test gal./min. with ft. drawdown after hrs.
Artesian flow g.p.m. Date
Temperature of water Was a chemical analysis made? Yes No

(12) WELL LOG:

Diameter of well 12 inches.
Depth drilled 59 ft. Depth of completed well 59 ft.
Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

MATERIAL	FROM	TO
River Bottom Soil	0'	2'
Brown Clay	2'	19'
Sand & Gravel-Medium & Scarse	19'	46'
Blue Clay	46'	59'

Work started June 9, 1961. Completed June 25, 1961

(13) PUMP:

Manufacturer's Name Jacuzzi Bros. Inc.
Type: Turbine H.P.

Well Driller's Statement:
This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME Art Clinton Well Drilling Co.
(Person, firm, or corporation) (Type or print)
Address Route 1, Box 2, Independence, Oregon
Driller's well number 11-61
[Signed] Art Clinton
(Well Driller)
License No. 14 Date June 27, 1961