NOTICE TO WATER WELL CONTRACTOR
The original and first copy of this report are to be filed with the STATE ENGINEER, SALEM, OREGON within 30 days from the date of well completion.

RECEIVED JUN 15 1964 STATE ENGINEER SALEM, OREGON

UMAT 1089

WATER WELL REPORT
STATE OF OREGON
(Please type or print)

State Well No. 2N/34-1

State Permit No.

(1) OWNER:

Name Lucy Johnson

Address Rt. 1 Box 17
Adams, Oregon

(2) LOCATION OF WELL:

County Umatilla Driller's well number 41

S½ XX NW ¼ Section 1 T. 2N R. 34E W.M.

Bearing and distance from section or subdivision corner

Willamette Meridian in Oregon

(3) TYPE OF WORK (check):

Well ☒ Deepening ☐ Reconditioning ☐ Abandon ☐

If abandonment, describe material and procedure in Item 12.

(4) PROPOSED USE (check):

Domestic ☒ Industrial ☐ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☐

(5) TYPE OF WELL:

Rotary ☐ Driven ☐
Cable ☒ Jetted ☐
Dug ☐ Bored ☐

(6) CASING INSTALLED: Threaded ☐ Welded ☒

6" Diam. from 1 ft. to 25.1 ft. Gage 0.28 In.
" Diam. from ft. to ft. Gage
" Diam. from ft. to ft. Gage

(7) PERFORATIONS: Perforated? ☐ Yes ☒ No

Type of perforator used

Size of perforations in. by in.

perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

(8) SCREENS: Well screen installed? ☐ Yes ☒ No

Manufacturer's Name
Model No.
Diam. Slot size Set from ft. to ft.
Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:

Well seal—Material used in seal Cement & Grout

Depth of seal 25.1 ft. Was a packer used? No

Diameter of well bore to bottom of seal 6 in.

Were any loose strata cemented off? ☐ Yes ☒ No Depth

Was a drive shoe used? ☒ Yes ☐ No

Was well gravel packed? ☐ Yes ☒ No Size of gravel:

Gravel placed from ft. to ft.

Did any strata contain unusuable water? ☒ Yes ☐ No

Type of water? Surface depth of strata 14

Method of sealing strata off Drive shoe & Grout

(10) WATER LEVELS:

Static level 3 ft. below land surface Date 5-21-64

Artesian pressure lbs. per square inch Date

(11) WELL TESTS: Drawdown is amount water level is lowered below static level

Was a pump test made? ☐ Yes ☒ No If yes, by whom?

Yield: gal./min. with ft. drawdown after hrs.
" " " "
" " " "

Bailer test 60 gal./min. with 12 ft. drawdown after hrs.

Artesian flow g.p.m. Date

Temperature of water Was a chemical analysis made? ☐ Yes ☐ No

(12) WELL LOG: Diameter of well below casing 6"

Depth drilled 27 ft. Depth of completed well 27 ft.

Formation: *Describe by color, character, size of material and structure, and show thickness of aquifiers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

MATERIAL	FROM	TO
Cobbles & sand	1	14
Fine Gravel	14	22
Coarse Gravel	22	27

Drilled 8" to 24.0 ft.

Work started 5/18 1964. Completed 5/21 1964

Date well drilling machine moved off of well 5/21 1964

(13) PUMP:

Manufacturer's Name

Type: H.P.

Water Well Contractor's Certification:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME Haden Drilling Company
(Person, firm or corporation) (Type or print)

Address 4304 W. Court, Pasco, Washington

Drilling Machine Operator's License No. 331

[Signed] [signature]
(Water Well Contractor)

Contractor's License No. 409 Date 6-6, 1964

(USE ADDITIONAL SHEETS IF NECESSARY)