ICE TO WATER WELL CONTRACTOR
The original and first copy of this report are to be filed with the
STATE ENGINEER, SALEM, OREGON 97310
within 30 days from the date of well completion.

RECEIVED
JUN 15 1964
STATE ENGINEER
SALEM, OREGON

WATER WELL REPORT
STATE OF OREGON
(Please type or print)

UMAT 1095

State Well No. 2N/34-2E

State Permit No.

(1) OWNER:

Name Jasper Shippentower

Address Box 42
Cayuse, Oregon

(2) LOCATION OF WELL:

County Umatilla Driller's well number 39

SW ¼ NW ¼ Section 2 T. 2N R. 34E W.M.

Bearing and distance from section or subdivision corner

Willamette Meridian in Oregon

(3) TYPE OF WORK (check):

Well ☒ Deepening ☐ Reconditioning ☐ Abandon ☐

Abandonment, describe material and procedure in Item 12.

(4) PROPOSED USE (check):

Domestic ☒ Industrial ☐ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☐

(5) TYPE OF WELL:

Rotary ☐ Driven ☐
Cable ☒ Jetted ☐
Dug ☐ Bored ☐

(6) CASING INSTALLED: Threaded ☐ Welded ☒

6" Diam. from 1 ft. to 35 ft. Gage 0.28 In
" Diam. from ft. to ft. Gage
" Diam. from ft. to ft. Gage

(7) PERFORATIONS: Perforated? ☐ Yes ☒ No

Type of perforator used

Size of perforations in. by in.

perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

(8) SCREENS: Well screen installed? ☐ Yes ☒ No

Manufacturer's Name

Model No.

Diam. Slot size Set from ft. to ft.
Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:

Well seal—Material used in seal Cement & Grout

Depth of seal 35 ft. Was a packer used? No

Diameter of well bore to bottom of seal 6 in.

Were any loose strata cemented off? ☐ Yes ☒ No Depth

Was a drive shoe used? ☒ Yes ☐ No

Was well gravel packed? ☐ Yes ☒ No Size of gravel:

Gravel placed from ft. to ft.

Did any strata contain unusuable water? ☒ Yes ☐ No

Type of water? Surface depth of strata 4

Method of sealing strata off Drive shoe & grout

(10) WATER LEVELS:

Static level 1.3 ft. below land surface Date 5-7-64

Artesian pressure lbs. per square inch Date

(11) WELL TESTS: Drawdown is amount water level is lowered below static level

Was a pump test made? ☐ Yes ☒ No If yes, by whom?

Yield: gal./min. with ft. drawdown after hrs.
" " " "
" " " "

Bailer test 20 gal./min. with 20 ft. drawdown after hrs.

Artesian flow g.p.m. Date

Temperature of water Was a chemical analysis made? ☐ Yes ☒ No

(12) WELL LOG: Diameter of well below casing 6"

Depth drilled 43 ft. Depth of completed well 43 ft.

Formation: *Describe by color, character, size of material and structure, and show thickness of aquifiers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

MATERIAL	FROM	TO
Silt	1	4
Cobbles & Gravel	4	12
Broken rock	12	22

Drilled 8" to 24.0 ft.

Work started 5-7 19 64 Completed 5-11 1964

Date well drilling machine moved off of well 5-11 19 64

(13) PUMP:

Manufacturer's Name

Type: H.P.

Water Well Contractor's Certification:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME Haden Drilling Co.
(Person, firm or corporation) (Type or print)

Address 4304 W. Court, Pasco, Washington

Drilling Machine Operator's License No. 330

[Signed] [signature]
(Water Well Contractor)

Contractor's License No. 409 Date June 6, 1964

(USE ADDITIONAL SHEETS IF NECESSARY)