STATE OF OREGON WATER SUPPLY WELL REPORT

WELL I.D. # L. (as required by ORS 537.765) START CARD # Instructions for completing this report are on the last page of this form (9) LOCATION OF WELL by legal description: . (1) OWNER: Well Number County Umatilla Latitude Longitude Name Nor**≠** Range_ 2 SE Address SW Zip 97888 1/4 1/4 State City Hermiston Block Subdivision Tax Lot Lat (2) TYPE OF WORK Street Address of Well (or nearest address) New Well Deepening Alteration (repair/recondition) Abandonment (3) DRILL METHOD: (10) STATIC WATER LEVEL: Rotary Air Rotary Mud Cable Auger 20.66 ft. below land surface. Other (4) PROPOSED USE: lb. per square inch. Artesian pressure (11) WATER BEARING ZONES: Industrial **Irrigation** Domestic Community Injection Livestock Other Thermal (5) BORE HOLE CONSTRUCTION: Depth at which water was first found Special Construction approval Yes No Depth of Completed Well 70 ft. **Estimated Flow Rate** SWL To From Explosives used Yes No Type SEAL HOLE From Sacks or pounds Diameter (12) WELL LOG: □E \square B $\square D$ How was seal placed: Ground Elevation Other . SWL Material From To ft. ft. to Material Backfill placed from ſt. Size of gravel Gravel placed from ft. to (6) CASING/LINER: Threaded Welded T• Gauge Steel Plastic Liner: Final location of shoe(s) Information on this report (7) PERFORATIONS/SCREENS: is from Department Files Perforations Method Material Screens Tele/pipe Casing Diameter Liner From (8) WELL TESTS: Minimum testing time is 1 hour Completed (unbonded) Water Well Constructor Certification: Flowing I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge Artesian Pump Bailer ☐ Air Time Drill stem at Yield gal/min Drawdown 1 hr. and belief. WWC Number Date Signed (bonded) Water Well Constructor Certification: Depth Artesian Flow Found Temperature of water Yes By whom I accept responsibility for the construction, alteration, or abandonment work Was a water analysis done? performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief. Did any strata contain water not suitable for intended use? Salty Muddy Odor Colored Other WWC Number Depth of strata: Signed