WELL I.D. #L 22 90 6

STATE OF OREGON

WATER SUPPLY WELL REPORT

START CARD # 140 909 (as required by ORS 537.765) Instructions for completing this report are on the last page of this form. (9) LOCATION OF WELL by legal description: (1) LAND OWNER County Unatilla Latitude Longitude _ Township _ SN or S Range _ J & E or W. WM. 1300 State Section 17 SW 1/4 NE 1/4 Umatilla Zip 47887 Tax Lot unknown (2) TYPE OF WORK Street Address of Well (or nearest address) High school ☐ New Well ☐ Deepening ► Alteration (repair/recondition) ☐ Abandonment 1300 74 ST Umatilla (3) DRILL METHOD: Rotary Air Rotary Mud Cable Auger (10) STATIÇ WATER LEVEL: 55 /2 ft. below land surface. Other_ Artesian pressure ______lb. per square inch (4) PROPOSED USE: ☐ Domestic ☐ Community ☑ Industrial ☐ Irrigation (11) WATER BEARING ZONES: ☐ Livestock ☐ Other_ ☐ Thermal ☐ Injection Depth at which water was first found -(5) BORE HOLE CONSTRUCTION: Special Construction approval Yes No Depth of Completed Well **Estimated Flow Rate** SWL From Explosives used Yes Yes Yo Type___ _Amount _ SEAL HOLE Sacks or pounds From Material Diameter From (12) WELL LOG: How was seal placed: Method \square B Ground Elevation _ ☐ Other _ Material From SWL Backfill placed from ____ ft. to_____ Material Back ft. to__ Size of gravel. Gravel placed from _ (6) CASING/LINER: Plastic Welded Threaded redeveloped To Gauge Steel Diameter From **人** Drive Shoe used ☐ Inside ☐ Outside ☐ None Final location of shoe(s). (7) PERFORATIONS/SCREENS: Method Torch Material ☐ Screens Tele/pipe size Number Diameter From To Casing Liner 14×3 560 Ø DCT 3 0 2002 WATER RESCURCES DEPT SALEM, OREGON Date started 10-22 Completed (8) WELL TESTS: Minimum testing time is 1 hour Flowing (unbonded) Water Well Constructor Certification: □ Bailer **₩**Аіг ☐ Artesian ☐ Pump I certify that the work I performed on the construction, alteration, or abandon-Yield gal/min Drawdown Drill stem at Time ment of this well is in compliance with Oregon water supply well construction 1 hr. standards. Materials used and information reported above are true to the best of my 300 200 4 knowledge and belief. (bonded) Water Well Constructor Certification: _Depth Artesian Flow Found I accept responsibility for the construction, alteration, or abandonment work Was a water analysis done? ☐ Yes By whom _ performed on this well during the construction dates reported above. All work Did any strata contain water not suitable for intended use? ☐ Too little performed during this time is in compliance with Oregon water supply well ☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other ☐ construction standards. This report is true to the best of my knowledge and belief WWC Number _ Depth of strata: ___ _ Date 10-26