STATE OF OREGON WATER SUPPLY WELL REPORT (as required by ORS 537.765 & OAR 690-205-0210)

04-29-2008

WELL LABEL # L 8776	
START CARD # 1003103	

(1) LAND OWNER Owner Well I.D.	(9) LOCATION OF WELL (legal description)	
First Name CAMERON Last Name GILLESPIE	County Umatilla Twp 1.00 N N/S Range 32.00 E E/W WM	
Company	Sec 33 SE 1/4 of the SE 1/4 Tax Lot 8100	
Address 207 SW 9TH	Tax Map Number Lot	
City PENDLETON State OR Zip 97801	Lat°' or DMS or DD	
(2) TYPE OF WORK New Well Deepening Conversion	Long OMS or DD	
Alteration (repair/recondition) Abandonment	Street address of well • Nearest address	
(3) DRILL METHOD Rotary Air Rotary Mud Cable Auger Cable Mud	67794 395 S. PENDLETON, OR	
Reverse Rotary Other	(10) STATIC WATER LEVEL Date SWL(psi) + SWL(ft)	
(4) PROPOSED USE Domestic Irrigation Community	Existing Well / Predeepening	
Industrial/ Commercial Livestock Dewatering	Completed Well 04-28-2008 28	
Thermal Injection Other	Flowing Artesian? Dry Hole?	
	WATER BEARING ZONES Depth water was first found 360	
(5) BORE HOLE CONSTRUCTION Special Standard (Attach copy)		
Depth of Completed Well 450.00 ft. BORE HOLE SEAL sacks/	04-10-2008 360 424 500 28	
BORE HOLE SEAL sacks/ Dia From To Material From To Amt lbs		
14.5 0 32 Cement 0 32 15 S		
10 32 450		
	(11) WELL LOG Ground Floration	
How was seal placed: Method A B C D E	Glouild Elevation	
	Material From To	
Other	CEMENTED GRAVEL 2 23	
Backfill placed from ft. to ft. Material Filter pack from ft. to ft. Material Size	BLACK BASALT AND BROWN BASALT 23 125	
· — — — — — — — — — — — — — — — — — — —	BLACK BASALT W/GREEN CLAYSTONE 125 185	
Explosives used: Yes Type Amount Amount	BLACK BASALT 185 188	
(6) CASING/LINER	GRAY BASALT 188 205	
Casing Liner Dia + From To Gauge Stl Plstc Wld Thrd	BLACK BASALT W/GREEN CLAYSTONE 205 290 BLACK AND GRAY BASALT 290 302	
<u>● 10 2 32 .25 </u> <u>● ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ </u>	DI ACK AND DECURE DAGALET WACEPERS OF A VE	
	DI ACK DACALT	
	GRAY BASALT 335 350 GRAY BASALT 350 360	
	BROWN BASALT W/ TAN CLAY 360 375	
	BLACK BASALT W/SCORIA BROKEN 375 424	
Shoe Inside Outside Other Location of shoe(s)	BLACK AND BROWN BASALT W/BLUE CLAYST 424 428	
Temp casing Yes Dia From To	BLACK BASALT 428 450	
(7) PERFORATIONS/SCREENS		
Perforations Method		
Screens Type Material		
Perf/S Casing/ Screen Scrn/slot Slot # of Tele/ creen Liner Dia From To width length slots pipe size	Date Started 03-31-2008 Completed 04-28-2008	
	(unbonded) Water Well Constructor Certification	
	I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well	
	construction standards. Materials used and information reported above are true to	
	the best of my knowledge and belief.	
(8) WELL TESTS: Minimum testing time is 1 hour	License Number	
Pump Bailer Air Flowing Artesian	Electronically Filed	
Yield gal/min Drawdown Drill stem/Pump depth Duration (hr)	Signed GARRY L ZOLLMAN (E-filed)	
1,000 450 1 (bonded) Water Well Constructor Certification		
700 345 1	I accept responsibility for the construction, deepening, alteration, or abandonment	
500 245 1 work performed on this well during the construction dates reported above. All wo		
Temperature 61 °F Lab analysis Yes By	performed during this time is in compliance with Oregon water supply well	
Water quality concerns? Yes (describe below)	construction standards. This report is true to the best of my knowledge and belief.	
From To Description Amount Units	License Number 544 Date 04-29-2008	
	Electronically Filed	
	Signed LARRY BURD (E-filed)	
	Contact Info (optional)	