

STATE OF OREGON

WATER SUPPLY WELL REPORT

(as required by ORS 537.765 & OAR 690-205-0210)

01-25-2010

WELL LABEL # L 100119

START CARD # 1009315

(1) LAND OWNER Owner Well I.D. First Name PETE Last Name SYMIONOW Company Address 1926 E PUNKIN CENTER RD City HERMISTON State OR Zip 97838

(2) TYPE OF WORK [ ] New Well [X] Deepening [ ] Conversion [ ] Alteration (repair/recondition) [ ] Abandonment

(3) DRILL METHOD [X] Rotary Air [ ] Rotary Mud [ ] Cable [ ] Auger [ ] Cable Mud [ ] Reverse Rotary [ ] Other

(4) PROPOSED USE [X] Domestic [ ] Irrigation [ ] Community [ ] Industrial/ Commercial [ ] Livestock [ ] Dewatering [ ] Thermal [ ] Injection [ ] Other

(5) BORE HOLE CONSTRUCTION Special Standard [ ] (Attach copy) Depth of Completed Well 275.00 ft.

Table with columns: Dia, From, To, Material, SEAL, From, To, Amt, sacks/lbs

How was seal placed: Method [ ] A [ ] B [ ] C [ ] D [ ] E [ ] Other Backfill placed from ft. to ft. Material Filter pack from ft. to ft. Material Size Explosives used: [ ] Yes Type Amount

(6) CASING/LINER Table with columns: Casing, Liner, Dia, From, To, Gauge, Stl, Plstc, Wld, Thrd

Shoe [ ] Inside [ ] Outside [ ] Other Location of shoe(s) Temp casing [ ] Yes Dia From To

(7) PERFORATIONS/SCREENS Perforations Method Screens Type Material

Table with columns: Perf/S, Casing/Screen, Dia, From, To, Scrn/slot width, Slot length, # of slots, Tele/pipe size

(8) WELL TESTS: Minimum testing time is 1 hour [ ] Pump [ ] Bailer [X] Air [ ] Flowing Artesian Yield gal/min Drawdown Drill stem/Pump depth Duration (hr)

Temperature 58 °F Lab analysis [ ] Yes By Water quality concerns? [ ] Yes (describe below) Table with columns: From, To, Description, Amount, Units

(9) LOCATION OF WELL (legal description) County Umatilla Twp 4.00 N N/S Range 28.00 E E/W WM Sec 1 NE 1/4 of the NE 1/4 Tax Lot 800 Tax Map Number Lot Lat Long [X] Street address of well [ ] Nearest address

1926 E PUNKIN CTR RD HERMISTON, OR

(10) STATIC WATER LEVEL Date SWL(psi) + SWL(ft) Existing Well / Predeepening 01-25-2010 40 Completed Well 01-25-2010 40 Flowing Artesian? [ ] Dry Hole? [ ]

WATER BEARING ZONES Depth water was first found 265 Table with columns: SWL Date, From, To, Est Flow, SWL(psi), + SWL(ft)

(11) WELL LOG Ground Elevation Material From To BLACK BASALT 231 265 BLACK/BROWN SCORIA 265 275

Date Started 01-25-2010 Completed 01-25-2010

(unbonded) Water Well Constructor Certification I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

License Number 1735 Date 01-25-2010 Electronically Filed Signed CHAD COURTNEY (E-filed)

(bonded) Water Well Constructor Certification I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

License Number 1881 Date 01-25-2010 Electronically Filed Signed GARRY L ZOLLMAN (E-filed) Contact Info (optional)