UMAT 56547

WELL I.D. # L___

(1) LAND OWNER Name Neal + Hazel Riddle Address Route 2, Bex 73-B City Pendleton State OR Zip (2) TYPE OF WORK New Well Deepening Alteration (repair/recondition) Abandonment							(9) LOCATION OF WELL by legal description: County_UnstituteLongitude Township_ZNN or S Range32				
(3) DRILL METHOD: Rotary Air Rotary Mud Cable Auger Other							(10) STATIC WATER LEVEL:				
(4) PROPOSED USE: Domestic Community Industrial Irrigation Thermal Injection Livestock Other							Artesian pressurelb. per square inchlt. (11) WATER BEARING ZONES: Depth at which water was first found				
(5) BORE HOLE CONSTRUCTION: Special Construction approval Yes No Depth of Completed Well 315 ft. Explosives used Yes No Type Amount HOLE SEAL							From	To			SWL
Diameter From	То	Material	From	То	Sacks or pour	ods .					
How was seal place	ced:	Method 🗆	A 🗆	В	C D	O E	(12) WELL LOG:	und Elevation			
OtherBackfill placed from	•						Material The final proof survey		From	То	SWL
(6) CASING/L	INER:	To Gauge	e Steel		Welded Th		indicates 8 15 test and of 315 tes	to the water	dapth v right		
Liner:							the wall was	indicates Edvilled pro Lete of Reilled is	ior to 6/22/1954.		
Drive Shoe used							Genlogic map		logs of		
☐ Perforations Method								ly produce	s from		
From To	Slot	Number Di		Tele/pip size		Liner	Calumbia	River Bes	It Group.		
(8) WELL TESTS: Minimum testing time is 1 hour Flowing Pump Bailer Air Artesian Yeld gal/min Drawdown Drill stem at Time							Date startedCompleted				
a tree Bas mod	i hr.					SOURCE OF DATA/INFO Water right application file U-726. This is the lost on certificate 24684.					
Temperature of water Depth Artesian Flow Found Was a water analysis done?							COMPILED BY: Karl Worniak Ground water Section DATE: January 29 2010.				