UMAT 57849

WELL I.D. # L_

(1) LAND OWNER (9) LOCATION OF WELL by legal description: Well Number Ray Williams County Umatila _Latitude_ Name Longitude Address (N)or S Range E W. WM. Zip Section __29 City NE NE 1/4_ 1/4 (2) TYPE OF WORK Block Tax Lot Subdivision New Well Deepening Alteration (repair/recondition) Abandonment Street Address of Well (or nearest address) (3) DRILL METHOD: Rotary Air Rotary Mud Cable Auger (10) STATIC WATER LEVEL: Date 10-15-1985 Other. 60 ft. below land surface. Artesian pressure ___ lb. per square inch Date (4) PROPOSED USE: ☐ Domestic ☐ Community ☐ Industrial 💆 Irrigation (11) WATER BEARING ZONES: ☐ Thermal ☐ Injection ☐ Livestock ☐ Other Depth at which water was first found. (5) BORE HOLE CONSTRUCTION: Special Construction approval Yes No Depth of Completed Well 350 ft. SWL From **Estimated Flow Rate** Explosives used Yes No Type. Amount HOLE SEAL Material Sacks or pounds Diameter From From (12) WELL LOG: How was seal placed: Method □B **Ground Elevation** ☐ Other. Material From SWL Backfill placed from ft. to ft. Material Gravel placed from ft. to. ft. Size of gravel (6) CASING/LINER: Plastic Welded Threaded Gauge Steel To From П Drive Shoe used ☐ Inside ☐ Outside ☐ None Final location of shoe(s). (7) PERFORATIONS/SCREENS: ☐ Perforations Method_ Screens Slot Tele/pipe Number Diameter Casing Liner From Date started Completed (8) WELL TESTS: Minimum testing time is 1 hour Flowing ☐ Artesian ☐ Air ☐ Pump □ Bailer Drill stem at Drawdown Time Yield gai/min SOURCE OF DATA/INFO l hr. Depth Artesian Flow Found Temperature of water_ Was a water analysis done? Yes By whom. COMPILED BY: Jen Woody, OWRD Did any strata contain water not suitable for intended use? ☐ Too little ☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other Depth of strata: 8-2-201 DATE: