

RECEIVED  
JUL 3 1959

WATER WELL DRILLERS REPORT  
STATE OF OREGON

Do Not State Well No. 11/15-8A  
Fill In State Permit No. \_\_\_\_\_

(1) OWNER: SALEM, OREGON  
Name Dr. John Shields Gilhausen  
Address 407 U.S. Natl. Bank Bldg., The Dalles, Oregon **002724**

(2) LOCATION OF WELL:  
County Wasco Owner's number, if any—  
R. F. D. or Street No. \_\_\_\_\_  
Bearing and distance from section or subdivision corner 660 ft. S & 1250 ft. W. from the NE corner of Sect. 8, TWP 1, R 15 E being within the NE 1/4 of NE 1/4 of Sec. 8, Twp. 1N, R 15 E

(3) TYPE OF WORK (check):  
New well  Deepening  Reconditioning  Abandon   
If abandonment, describe material and procedure in Item 11.

(4) PROPOSED USE (check): Domestic  Industrial  Municipal   
Irrigation  Test Well  Other

(6) CASING INSTALLED:  
Threaded  Welded   
Type and size of shoe or well ring \_\_\_\_\_  
Describe joint \_\_\_\_\_

(7) PERFORATIONS:  
Type of perforator used \_\_\_\_\_  
SIZE of perforations in., length, by in.  
FROM ft. to ft. perf per foot No. of rows

SCREENS:  
Give Manufacturer's Name, Model No. and Size \_\_\_\_\_

(8) CONSTRUCTION:  
Was a surface sanitary seal provided?  Yes  No To what depth \_\_\_\_\_ ft.  
Were any strata sealed against pollution?  Yes  No  
If yes, note depth of strata  
FROM ft. to ft.

(9) WATER LEVELS:  
Depth at which water was first found \_\_\_\_\_ ft.  
Standing level before perforating 23 ft.  
Standing level after perforating \_\_\_\_\_ ft.

Log Accepted by:  
[Signed] Dr. John Gilhausen dated July 1, 1959  
Owner

(10) WELL TESTS:  
Was a pump test made?  Yes  No If yes, by whom? Driller  
Yield: 90 gal./min. with 42 ft. draw down after 12 hrs.  
Artesian flow \_\_\_\_\_ g.p.m.  
Shut-in pressure \_\_\_\_\_ lbs. per square inch.  
Bailer test \_\_\_\_\_ g.p.m. with \_\_\_\_\_ ft. drawdown  
Temperature of water \_\_\_\_\_ Was a chemical analysis made?  Yes  No  
Was electric log made of well?  Yes  No

(11) WELL LOG:  
Diameter of well, 6 inches.  
Total depth 162 ft. Depth of completed well 162 ft.  
Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

Ground elevation at well site \_\_\_\_\_ feet above mean sea level.  
Work started June 8, 1959. Completed June 24, 1959

Well Driller's Statement:  
This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.  
NAME Dorin Wilburn  
(Person, firm, or corporation) (Typed or printed)  
Address 812 E 7th Street, The Dalles, Oregon  
Driller's well number \_\_\_\_\_  
[Signed] Dorin Wilburn (Well Driller)  
License No. 80 Dated June 29, 1959