STATE ENGINEER Salem, Oregon 00323	Well	Record 4	COUNTY	NO. 2N/13-17R Wasco N NO. GR-4184
OWNER: The Dalles Country Club,	•	MAILING		
		CINA VIT		
LOCATION OF WELL: Owner's No		STATE:	The Dalles, On	regon
SE¼SE¼ Sec17 T2 X ,		W.M.		
Bearing and distance from section or sub			!	
corner Approx. 840' N. & 1125' W.	of SE Cor.	Sec. 17		
A14:43				
Altitude at well				X
TYPE OF WELL: Drilled Date Cons	• •	-		
Depth drilled350 ft. Depth case	d 40 ft.	•	Section17	!
CASING RECORD:				
FINISH:				
AQUIFERS:				
WATER LEVEL:				
160 feet below surface				
PUMPING EQUIPMENT: Type Sterl Capacity	ing Deep w	ell turbine	oanks Morse mot	or H.P. 30
WELL TESTS:		•	200	
Drawdown				
Drawdown ft. after		hours		G.P.M.
USE OF WATER Irrigation SOURCE OF INFORMATION Well R DRILLER or DIGGER George E. S ADDITIONAL DATA:	legistratio	n Statement	Cert. # GR-374	43
Log X Water Level Measurement	nts	Chemical Analy	rsis Aqu	ifer Test
REMARKS: Log "No detailed log of well i 12 inches to depth of 40 feet, wh to that depth. From that point of 10 inches. Water bearing roc supply of water was insufficient Well was then tested, with the re	ere basalt well was d; k was firsi . and drill	rock was encorilled through t encountered	ountered, and wanted as solid rock with at depth of 180	as cased th diameter) feet, but