WASC 52141

WELL I.D. # L

								CARRET Land	decominations			
(1) LAND OWNER Delco Name Ralph Delco Address Box 83 City Turk Valley State OR Zip 97063							(9) LOCATION OF	C Latitude	uescription:	ngitude		
							County Wasco Latitude Longitude Township 3 5 N or S Range 12 E E or W. WM.					
							Section 36 NE 1/4 NW 1/4					
City Tygh	Valle	9	State UK		Zip 9-1	5002	Section 56	_ <u>NE 1/4</u> _	NVO I	4		
(2) TYPE OF WORK New Well Deepening Alteration (repair/recondition) Abandonment							Tax LotLotBlockSubdivision Street Address of Well (or nearest address)					
New Well	Deepening	g Alterat	tion (repair/	recondition	on) LI Abando	onment	Street Address of \	Well (or nearest address)			
(3) DRILL ME	THOD:							DD I DIUDI				
Rotary Air	Rotary N	Aud Cat	ble 🗆 Au	iger			(10) STATIC WAT			Date		
⊗Other_ Dug							ft. below land surface. Date Artesian pressurelb. per square inch Date					
(4) PROPOSE	D USE:								square men	Date		
Domestic	Commun	ity 🗌 Indus	strial 🔯 l	Irrigation	n		(11) WATER BEAT	RING ZONES:				
Thermal	Injection	Lives	stock 🗆	Other			Depth at which water	was first found				
(5) BORE HOLE CONSTRUCTION: Special Construction approval Yes No Depth of Completed Well ft.									Estimated F		SWL	
Cassial Construc	tion appro	val TYcs	No Dep	th of Co	mpleted Well_		From	То	Estimated P	IOW RUIC	SWL	
Explosives used	☐ Yes ☐	No Type_		An	nount						-	
HOLE			SEAL	-	Sacks or poun	4.					-	
Diameter From	To I	Material	From	To (Sacks or poun	NU S					++	
	1-1		1									
							(12) WELL LOG:					
How was seal pla	aced:	Method [JA 🗆	в 🗆	C D	□ E	Gro	und Elevation				
Other							Mat	erial	From	To	SWL	
Backfill placed fr	rom	ft. to	ft.		al						-	
Gravel placed fro	om	ft. to	ft.	Size of	gravel		Application	G-4487		1	1	
(6) CASING/I							describes +	his as all		-	1	
	r From	To Gau		Plastic		readed	existing s	sump well		-	+	
Casing:							30 × 40 ×	10 deep			+	
							Current Co	naition		1	1	
***************************************							unknown	, but could			+	
***************************************			0				not see To			1	1	
Liner:			0				Imagery.				1	
Drive Shoe used	Inside	Outside	None	:							1	
Final location of			c.							1		
(7) PERFOR	ATIONS	Method	ð:									
☐ Perforation	ons	Туре		M	acertal					—		
Screens	Slot			Tele/pl	ipe							
From To	size	Number	Diameter	size		Liner						
1												
		+		-								
		+		+								
		<u> </u>		<u></u>								
(8) WELL TI	eere. M	linimum t	esting tin	ne is 1	hour		Date started	Cc	ompleted			
(8) WELL TI												
□ Pump □ Bailer □ Air □ Artesian								E DATA HAIT				
Yield gal/min Drawdown Drill stem at Time							SOURCE OF DATA/INFO					
						111.	Grounda	outer fil	The same of the sa		حتج تح	
							The Po	A describ	ed on c	ertiti	cato	
						-	205 /2	nd 52230				
	water	r	Depth Artes	sian Flor	w Found							
Temperature of	water		s By wh	om			COMPILED	BY: Vacl	1. 7. 24.	ak	•	
Was a water an	Was a water analysis done? Yes By whom Did any strata contain water not suitable for intended use? Too little							COMPILED BY: Karl Wozniak : Groundwater Section				
Salty	Muddy	Odor [Colored	Of	her		1	Grow	NOW CONTROL	200		
Depth of strata								11 1 2-	2011			
Depuis of sudia							DATE:	March 25	,2014			