

10/21/2025

START CARD # 1079694

1079694

ORIGINAL LOG #

WASCO

2763

(2a) PRE-ALTERATION

Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd
								
								
								

Material	From	To	Amt	sacks/lbs
----------	------	----	-----	-----------

(5) BORE HOLE CONSTRUCTION

BORE HOLE

SEAL

sacks/
lbs

Dia	From	To	Material	From	To	Amt	Sacks/ lbs
					Calculated		
					Calculated		
					Calculated		
					Calculated		

FILTER PACK

From	To	Material	Size
------	----	----------	------

(6) CASING/LINER

[illegible]

(7) PERFORATIONS/SCREENS

[illegible]

(8) WELL TESTS: Minimum testing time is 1 hour

Type of Test	Yield (gal/min)	Drawdown	Drill Stem/ Pump Depth	Duration (hr)

Water Quality Concerns

From	To	Description	Amount	Units

(10) STATIC WATER LEVEL

[illegible]

(11) WELL LOG

[illegible]

Name of person(s) who assisted with construction and Trainee License # / Helper #

Assistant Name

Type

#

JAKE CAMPBELL

HELPER WATER

8888972

Comments/Remarks

REMOVED PUMP, INSTALLED TREMMY PIPE TO BOTTOM. PUMPED CEMENT 4% BENTONITE TO SURFACE. CUT CASING 3' BELOW GRADE, AND BACKFILLED.
--