

NOTICE TO WATER WELL CONTRACTOR

The original and first copy of this report are to be filed with the

STATE ENGINEER, SALEM 10, OREGON within 30 days from the date of well completion.

RECEIVED

NOV - 5 1962

WATER WELL REPORT

STATE ENGINEER STATE OF OREGON (Please type or print)

SALEM, OREGON

WASH 012971

2/2W-23 M(1)

State Well No.

State Permit No.

G 2701

(1) OWNER:

Name John W. Mann Holly Inc.

Address 10819 S.W. Capital Hwy.

Portland 19, Oregon.

(2) LOCATION OF WELL:

County Washington Driller's well number

1/4 1/4 Section 22 T. 2S R. 2W W.M.

Bearing and distance from section or subdivision corner

(3) TYPE OF WORK (check):

Well ☒ Deepening ☐ Reconditioning ☐ Abandon ☐

If abandonment, describe material and procedure in Item 12.

(4) PROPOSED USE (check):

Domestic ☒ Industrial ☐ Municipal ☐

Irrigation ☒ Test Well ☐ Other ☐

(5) TYPE OF WELL:

Rotary ☐ Driven ☐

Cable ☒ Jetted ☐

Dug ☐ Bored ☐

(6) CASING INSTALLED:

Threaded ☐ Welded ☒

6 " Diam. from 0 ft. to 9.2 ft. Gage std.

" Diam. from ft. to ft. Gage

" Diam. from ft. to ft. Gage

(7) PERFORATIONS:

Perforated? ☐ Yes ☒ No

Type of perforator used

Size of perforations in. by in.

perforations from ft. to ft.

perforations from ft. to ft.

perforations from ft. to ft.

perforations from ft. to ft.

perforations from ft. to ft.

(8) SCREENS:

Well screen installed ☐ Yes ☒ No

Manufacturer's Name

Model No.

Diam. Slot size Set from ft. to ft.

Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:

Well seal—Material used in seal Bentonite - cutting

Depth of seal 9.0 ft. Was a packer used? NO

Diameter of well bore to bottom of seal 8 in.

Were any loose strata cemented off? ☐ Yes ☒ No Depth

Was a drive shoe used? ☐ Yes ☐ No

Was well gravel packed? ☐ Yes ☒ No Size of gravel:

Gravel placed from ft. to ft.

Did any strata contain unusable water? ☐ Yes ☒ No

Type of water? Depth of strata

Method of sealing strata off

(10) WATER LEVELS:

Static level 37.3 ft. below land surface Date 9/8/62

Artesian pressure lbs. per square inch Date

(11) WELL TESTS:

Drawdown is amount water level is lowered below static level

Was a pump test made? ☐ Yes ☐ No If yes, by whom?

Yield: gal./min. with ft. drawdown after hrs.

" " " "

" " " "

Bailer test 18 gal./min. with no ft. drawdown after hrs.

Artesian flow a.p.m. Date

Temperature of water Was a chemical analysis made? ☐ Yes ☐ No

(12) WELL LOG:

Diameter of well below casing 6"

Depth drilled 513 ft. Depth of completed well 513 ft.

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

MATERIAL	FROM	TO
Clay	0	20
" red	20	45
" gravel	45	55
	55	100
Rock light tan	100	105
" dark "trace of water	105	130
" light	130	140
" dark rather soft	140	160
" tan	160	190
" Lavender Lava	190	195
" tan	195	215
" Dark gray Lava	215	295
" " "Harder	295	302
" Gray	302	325
" Black	325	335
" Red	335	342
" Gray	342	365
" Black	365	387
" Gray	387	412
" Brown (little water)	412	415
" Gray	415	428
Hard & soft streaks	428	435
Rock gray (little water)	435	455

Work started 19 Completed 19

Date well drilling machine moved off of well 19

(13) PUMP:

Manufacturer's Name

Type: H.P.

Water Well Contractor's Certification:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME Alden H. Barron (Person, firm or corporation) (Type or print)

Address Rt 1 - Box 254 - Beaverton Ore

Drilling Machine Operator's License No.

[Signed] Barron & Streyer (Water Well Contractor)

Contractor's License No. 35 Date Oct, 1962

(USE ADDITIONAL SHEETS IF NECESSARY)