

STATE OF OREGON

WATER SUPPLY WELL REPORT

(as required by ORS 537.765 & OAR 690-205-0210)

03-29-2010

WELL LABEL # L 103412

START CARD # 1009585

(1) LAND OWNER Owner Well I.D. TAG: 103412
First Name _____ Last Name P10054-4352
Company TRI MET
Address 710 NE HOLLADAY ST
City PORTLAND State OR Zip 97232

(2) TYPE OF WORK ☐ New Well ☐ Deepening ☐ Conversion
☐ Alteration (repair/recondition) ☒ Abandonment

(3) DRILL METHOD
☐ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger ☐ Cable Mud
☐ Reverse Rotary ☒ Other GROUTED & PULLED

(4) PROPOSED USE ☐ Domestic ☐ Irrigation ☐ Community
☐ Industrial/ Commercial ☐ Livestock ☒ Dewatering
☐ Thermal ☐ Injection ☐ Other

(5) BORE HOLE CONSTRUCTION Special Standard ☒ (Attach copy)
Depth of Completed Well 20.00 ft.

BORE HOLE			SEAL			sacks/
Dia	From	To	Material	From	To	lbs
1.5	0	20	Bentonite Chips	0	5	1 S
			Bentonite Grout	5	20	1 S

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☒ Other POURED

Backfill placed from _____ ft. to _____ ft. Material _____
Filter pack from _____ ft. to _____ ft. Material _____ Size _____
Explosives used: ☐ Yes Type _____ Amount _____

(6) CASING/LINER											
Casing	Liner	Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd	
											
											
											
											
											

Shoe ☐ Inside ☐ Outside ☐ Other Location of shoe(s) _____
Temp casing ☐ Yes Dia _____ From _____ To _____

[illegible]

(8) WELL TESTS: Minimum testing time is 1 hour

☐ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian
 Yield gal/min Drawdown Drill stem/Pump depth Duration (hr)

Temperature 56 °F Lab analysis ☐ Yes By _____

Water quality concerns? ☐ Yes (describe below)

From	To	Description	Amount	Units

(9) LOCATION OF WELL (legal description)

County Washington Twp 1.00 S N/S Range 10.00 W E/W WM
Sec 8 NW 1/4 of the NW 1/4 Tax Lot 900
Tax Map Number _____ Lot _____
Lat _____ ° 0 ' _____ " or _____ DMS or DD
Long _____ ° 0 ' _____ " or _____ DMS or DD
☒ Street address of well ☐ Nearest address
16130 SW MERLO RD, BEAVERTON, OR

(10) STATIC WATER LEVEL			
	Date	SWL(psi)	+ SWL(ft)
Existing Well / Predeepening			
Completed Well	03-04-2010		8
Flowing Artesian?	☐	Dry Hole?	☐

WATER BEARING ZONES					Depth water was first found 8	
SWL Date	From	To	Est Flow	SWL (psi)	+	SWL (ft)
03-04-2010	8	20				8

[illegible]

Date Started 03-04-2010 Completed 03-04-2010

(unbonded) Water Well Constructor Certification
I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

License Number 10328 Date 03-29-2010
Electronically Filed
Signed JOEL R WELSH (E-filed)

(bonded) Water Well Constructor Certification
I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

License Number 10357 Date 03-29-2010
Electronically Filed
Signed TERRENCE JACQUES (F-filed)
Contact Info (optional)

(5) BORE HOLE CONSTRUCTION

BORE HOLE

SEAL

sacks/

[illegible]

FILTER PACK

From	To	Material	Size
------	----	----------	------

(6) CASING/LINER

Casing Liner	Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd
--------------	-----	---	------	----	-------	-----	-------	-----	------

(7) PERFORATIONS/SCREENS

Perf/S creen	Casing/ Liner	Screen Dia	From	To	Scrn/slot width	Slot length	# of slots	Tele/ pipe size
-----------------	------------------	---------------	------	----	--------------------	----------------	---------------	--------------------

[illegible]

(8) WELL TESTS: Minimum testing time is 1 hour

Yield gal/min	Drawdown	Drill stem/Pump depth	Duration (hr)
---------------	----------	-----------------------	---------------

Water Quality Concerns

From	To	Description	Amount	Units
------	----	-------------	--------	-------

Year	10	Description		

(10) STATIC WATER LEVEL

Water Bearing Zones

SWL Date	From	To	Est Flow	SWL(psi)	+ SWL(ft)
----------	------	----	----------	----------	-----------

[illegible]

(11) WELL LOG

Material	From	To
----------	------	----

[illegible]

RECEIVED
MAY 13 2010
WATER RESOURCES DEPT
SALZM, OREGON

Comments/Remarks

Dewatering well was abandoned by bentonite grout from 20' to 0'

Casing and riser removed.

Original Startcard: 1009449

Well ID Tag: 103412

Map of well

