

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765 & OAR 690-205-0210)

WASH 75954

9/25/2017

WELL I.D. LABEL# L

START CARD #

ORIGINAL LOG #

126738

1036034

(1) LAND OWNER

Owner Well I.D. _____

First Name _____ Last Name _____

Company MOUNT CRUMPIT LLC

Address 16903 NW DAVIDSON RD

City BANKS State OR Zip 97106

(2) TYPE OF WORK☒ New Well ☐ Deepening ☐ Conversion☐ Alteration (complete 2a & 10) ☐ Abandonment (complete 5a)**(2a) PRE-ALTERATION**

Casing: Dia + From To Gauge Stl Plstc Wld Thrld
Material From To Amt sacks/lbs
Seal: _____

(3) DRILL METHOD
☒ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger ☐ Cable Mud
☐ Reverse Rotary ☐ Other _____
(4) PROPOSED USE
☒ Domestic ☐ Irrigation ☐ Community
☐ Industrial/ Commercial ☐ Livestock ☐ Dewatering
☐ Thermal ☐ Injection ☐ Other _____
(5) BORE HOLE CONSTRUCTIONSpecial Standard ☐ (Attach copy)

Depth of Completed Well 390.00 ft.

BORE HOLE			SEAL			sacks/ lbs
Dia	From	To	Material	From	To	
10	0	95	Bentonite Chips	0	30	18 S
6	95	390			Calculated	13.69
			Cement	30	90	22 S
					Calculated	16.1

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E☒ Other POURED AND PRODDED

Backfill placed from _____ ft. to _____ ft. Material _____

Filter pack from _____ ft. to _____ ft. Material _____ Size _____

Explosives used: ☐ Yes Type _____ Amount _____**(5a) ABANDONMENT USING UNHYDRATED BENTONITE**

Proposed Amount

Actual Amount

(6) CASING/LINER

Casing	Liner	Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd
☒	☐	6	☒	1.5	118.5	.250	☐	☐	☒	☐
☐	☒	4	☐	10	390	SCD40	☐	☒	☒	☐
☐	☐		☐				☐	☐	☐	☐
☐	☐		☐				☐	☐	☐	☐
☐	☐		☐				☐	☐	☐	☐
☐	☐		☐				☐	☐	☐	☐

Shoe ☐ Inside ☒ Outside ☐ Other Location of shoe(s) 118.5Temp casing ☐ Yes Dia _____ From + _____ To _____**(7) PERFORATIONS/SCREENS**

Perforations Method drilled

Screens Type _____

Material _____

Perf/	Casing/	Screen	Dia	From	To	Scrn/slot	Slot	# of	Tele/
Screen	Liner					width	length	slots	pipe size
Perf	Liner	4	330	390	.5	0.5	240	4	

(8) WELL TESTS: Minimum testing time is 1 hour☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem/Pump depth	Duration (hr)
9		350	1.5

Temperature 56 °F Lab analysis ☐ Yes By _____Water quality concerns? ☐ Yes (describe below) TDS amount 77 ppm

From	To	Description	Amount	Units

(9) LOCATION OF WELL (legal description)

County WASHINGTON Twp 2.00 N N/S Range 3.00 W E/W WM

Sec 20 NE 1/4 of the SW 1/4 Tax Lot 0600

Tax Map Number _____ Lot _____

Lat _____ " or _____ DMS or DD

Long _____ " or _____ DMS or DD

☒ Street address of well ☐ Nearest address

16903 NW DAVIDSON RD BANKS OR

(10) STATIC WATER LEVEL

	Date	SWL(psi)	+	SWL(ft)
Existing Well / Pre-Alteration				
Completed Well	9/4/2017			280
Flowing Artesian?	☐			
Dry Hole?	☐			

WATER BEARING ZONES

Depth water was first found 310.00

SWL Date	From	To	Est Flow	SWL(psi)	+	SWL(ft)
9/4/2017	310	360	9			280

(11) WELL LOG

Ground Elevation _____

Material	From	To
topsoil	0	1
brwn clay	1	5
brwn and red clayw/ gravel	5	58
grey clay w/med gravel embedded	58	79
med grey claystone	79	185
black shale	185	230
dark grey claystone w/brwn sandstone str	230	300
broken basalt	300	360
grey shale	360	390

Date Started 8/31/2017

Completed 9/4/2017

(unbonded) Water Well Constructor Certification

I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

License Number _____ Date _____

Signed _____

(bonded) Water Well Constructor Certification

I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

License Number 1956 Date 9/25/2017

Signed JOHN ROSS (E-filed)

Contact Info (optional) _____

ORIGINAL - WATER RESOURCES DEPARTMENT

THIS REPORT MUST BE SUBMITTED TO THE WATER RESOURCES DEPARTMENT WITHIN 30 DAYS OF COMPLETION OF WORK Form Version: