State of Oregon WATER WELL REPORT (as required by ORS 537.765) Page 1 o	State Well ID L42899 f 1 Start Card # 133811	
(1) OWNER: Well No. 2001 Name DAVE GROOTERS Address 20500 SW EAGLE POINT RD City NCMINNVILLE St OR Zip 97128 (2) TYPE OF WORK: NEW WELL	(9) LOCATION OF WELL by legal description: County YAMHILL Lat. " Long. " Township 3 S Range 4 W WM. Section 24 SW 1/4 SE 1/4 Tax Lot R3425 Lot 200 Block Subdivision Street Address of Well (or nearest Address) MYA, NE BAYLISS RD CARLTON, OR	
(3) DRILL METHOD: ROTARY AIR (4) PROPOSED USE: IRRIGATION	(10) STATIC WATER LEVEL: 72 ft. below land surface. Date 09/19/00 Artesian pressure lb per square in. Date	
(5) BORE HOLE CONSTRUCTION: Special Construction Approval NO Depth of Compl. Well 375 ft Explosives used NO Type Amount HOLE SEAL Diam. From To Material From To Amount 10 0 21 BENTONITE CHIP 0 21 13 SAX		
Seal placement method POURED/PROBED Backfill: from ft to ft Material Gravel: from ft to ft Size	(12) WELL LOG: Ground elevation Material	
(6) CASING/LINER: Diam. From To Gauge Material Connection Casing 6 +2 28 .25 STEEL WELDED	CLAY, RED/BROWN 3 13	
Liner 4 0 375 SDR26 PLASTIC WELDED Final Location of shoe(s) 28	CLAYSTONE, BROWN/HARD 352 360	
(7) PERFORATIONS/SCREENS:	-	RECEIVED
[X] Perf. Method ELECTRIC SAM [_] Screens Type Material Slot Tele/pipe	DAVE PAYSINGER, BLUE WATER DRILLING CO. (503) 868-7878	OCT 1 3 2000
From To Size Number Diam. Size Casing/liner 75 95 .1X7" 36	Date started 09/18/00 Completed 09/19/00	VATER RESOURCES D SALEM, OREGON
355 375 " " LINER	(unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or aband-	
(8) WELL TESTS: Minimum testing time is 1 hour Test type AIR Draw- Drill stem Yield GPM down at Time	onment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to my best knowledge and belief. WWC Number	
3.5 375	(bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported	
Temperature of water 54P Depth Artesian Flow Found Was water analysis done? NO By whom Reason for water not suitable for use	above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief. WWC Number 1438	

Depth of strata

Date 09/19/00