

STATE OF OREGON WATER SUPPLY WELL REPORT

Arrow

WELL ID # L 42491 START CARD # 12750 127520

(as required by ORS 537.765)

(1) OWNER:

Well Number: \_\_\_\_\_

Name: Dewey Kelley Address: 4021 SW Comus Street City: Portland State: OR Zip: 97219

(2) TYPE OF WORK: (repair/ ) [X] New Well [ ] Deepening [ ] Alteration recondition [ ] Abandonment

(3) DRILL METHOD: [X] Rotary Air [ ] Rotary Mud [ ] Cable [ ] Auger [ ] Other:

(4) PROPOSED USE: [X] Domestic [ ] Community [ ] Industrial [ ] Irrigation [ ] Thermal [ ] Injection [ ] Livestock [ ] Other

(5) BORE HOLE CONSTRUCTION: Special Construction approval [ ] Yes [X] No Depth of Completed Well 165 Explosives Used [ ] Yes [X] No Type Amount

Table with columns: Diameter, From, To, Material, SEAL, From, To, sacks or pounds

How was seal placed: Method [ ] A [ ] B [ ] C [ ] D [ ] E [X] Other poured -probed Backfill placed from \_\_\_\_\_ to \_\_\_\_\_ Material \_\_\_\_\_ Gravel placed from \_\_\_\_\_ to \_\_\_\_\_ Size of gravel \_\_\_\_\_

(6) CASING/LINER: CASING: Table with columns: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded

LINER: Table with columns: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded

Final location of Shoe(s): 39'

(7) PERFORATIONS/SCREENS: [X] Perforations Method: saw cut [ ] Screen Type: \_\_\_\_\_ Material: \_\_\_\_\_ Table with columns: From, To, Slot Size, No., Diameter, Tele/pipe size, Casing, Liner

(8) WELL TESTS: Minimum testing time is 1 hour [ ] Pump [ ] Bailer [X] Air [ ] Flowing Artesian Yield gpm Drawdown Drill Stem at Time

Temperature of water 55 Depth Artesian Flow Found Was a water analysis done? \_\_\_\_\_ By whom: \_\_\_\_\_ Did any strata contain water not suitable for intended use? (explain)

Depth of Strata: \_\_\_\_\_ ARROW DRILLING (503) 538-4422

(9) LOCATION OF WELL by legal description:

County: Yamhill Latitude: \_\_\_\_\_ Longitude: \_\_\_\_\_ Township: 2S Range: 3W Section: 32 NW 1/4 NW 1/4 Tax Lot: 1490 Lot: \_\_\_\_\_ Block: \_\_\_\_\_ Subdivision: \_\_\_\_\_ Street Address of Well (or nearest address) adjacent to 12541 N Valley Road, Newberg, Oregon 97132

(10) STATIC WATER LEVEL: 30 Ft. below land surface Date 10/14/00 Artesian pressure \_\_\_\_\_ lb. per sq. in. Date \_\_\_\_\_

(11) WATER BEARING ZONES:

Table with columns: From, To, Est. Flow Rate, SWL

(12) WELL LOG: Ground Elevation:

Table with columns: Material, From, To, SWL

RECEIVED RECEIVED

FEB 02 2001

AUG 02 2001

WATER RESOURCES DEPT SALEM, OREGON

Date Started: 10-13-00 Completed: 10-14-00

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration,, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

Signed Ryan B. Stadel Date \_\_\_\_\_ WWC Number 1358

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

Signed John R. Stoe Date 10-24-00 WWC Number 1483