State of Oregon WATER WELL REPORT (as required by ORS 537.765) Page	State Well ID NONE 2 1 of 1 Start Card # 151256	
(1) OWNER: Well No. 2190 Name YAMHILL VALLEY VINEYARDS Address 16250 SW OLDSVILLE RD City MCMINNVILLE St OR Zip 97128 (2) TYPE OF WORK: ABANDON	(9) LOCATION OF WELL by legal description: County YAMHILL Lat. " Long. " Township 5 S Range 5 W WM. Section 10 NE 1/4 NW 1/4 Tax Lot 1900 Lot Block Subdivision Street Address of Well (or nearest Address) 16250 SW OLDSVILLE RD MCMINNVILLE, OR	
(3) DRILL METHOD: OTHER	(10) STATIC WATER LEVEL:	
(4) PROPOSED USE: DOMESTIC	129 ft. below land surface. Date 02/28/03 Artesian pressure lb per square in. Date	
(5) BORE HOLE CONSTRUCTION: Special Construction Approval NO Depth of Compl. Well Explosives used NO Type Amount	ft (11) WATER BEARING ZONES: Depth at which water was first found NA From To Est Flow Rate SWL	
Seal placement method NA Backfill: from 0 ft to 280 ft Material SEE (12)	(12) WELL LOG: Ground elevation	
Gravel: from ft to ft Size	IN GOOD CONDITION/BOREHOLE OPEN 280' AND FREE OF ANY DEBRIS. SWL=129' AND QUIET. CLEAN GRAVEL BACKFILLED FROM 280' UP TO 180' THROUGH ALL SUSPECTED WBZ. NEAT CEMENT GROUT PLACED THRU TREMIT PIPE FROM 180' TO 3' FROM LAND	RECEIVED MAR 1 A 2003 MILLIANDES DEPT. SALEM, ÖREGON
[_] Screens TypeMaterial Slot Tele/pipe From To Size Number Diam. Size Casing/l	DAVE PAYSINGER, BLUE WATER DRILLING CO. (503) 868-7878	
	Date started 02/28/03	
Test type Draw- Yield GPM down at Time 1 hr. Temperature of water NA Depth Artesian Flow Found Was water analysis done? NO By whom Reason for water not suitable for use Depth of strata	(unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or aband- onment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to my best knowledge and belief. Signed Date (bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance	
ORIGINAL & FIRST COPY - WATER RESOURCES DEPTARTMENT S	SECOND COPY - CONSTRUCTOR THIRD COPY - CUSTOMER 9809C 10/91	