State Well ID L40549

State of Oregon WATER WELL REPORT (as required by ORS 537.765) Page 1 c	State Well ID L40549 of 1 Start Card # 158794	
(1) OWNER: Well No. 2276 Name YAMHILL VALLEY VINEYARDS Address 16250 SW OLDSVILLE RD City MCMINNVILLE St OR Zip 97128 (2) TYPE OF WORK: RECONDITION	(9) LOCATION OF WELL by legal description: County YAMHILL Lat. ' " Long. ' " Township 5 S Range 5 W WM. Section 10 NW 1/4 SE 1/4 Tax Lot 1900 Lot Block Subdivision Street Address of Well (or nearest Address) 16250 SW OLDSVILLE RD MCMINNVILLE, OR	
(3) DRILL METHOD: NA	(10) STATIC WATER LEVEL:	
(4) PROPOSED USE: FARM	19 ft. below land surface. Date 04/21/04 Artesian pressure lb per square in. Date	
(5) BORE HOLE CONSTRUCTION: Special Construction Approval NO Depth of Compl. Well 128 ft Explosives used NO Type Amount HOLE SEAL Diam. From To Material From To Amount NA		
Seal placement method NA Backfill: from ft to ft Material Gravel: from 25 ft to 128 ft Size 6X9 SAND	(12) WELL LOG: Ground elevation Material From To SWL INSTALL 4" LINER W/SCREEN SECTION AND SAND PACK SCREEN. ORIGINAL LINER HAD	
(6) CASING/LINER: Diam. From To Gauge Material Connection Casing	BEEN REMOVED DUE TO DAMAGE CAUSED BY OVERHEATED PUMP MOTOR SOMETIME PREVIOUS. NO OTHER WORK PERFORMED OTHER THAN PUMP TEST INDICATED IN SECTION (8).	
Liner 4 2 88 SDR26 PLASTIC WELDED Final Location of shoe(s) CAP ON 4" @ 128'		
(7) PERFORATIONS/SCREENS: [_] Perf. Method [X] Screens Type MACH SLOT Material PVC Slot Tele/pipe	DAVE PAYSINGER, BLUE WATER DRILLING CO. (503) 868-7878	
From To Size Number Diam. Size Casing/liner 88 128 40 4 PS LINER		
00 120 40 4 F5 BIABA	Date started 04/21/44	
(8) WELL TESTS: Minimum testing time is 1 hour Test type PUMP Draw- Drill stem	(unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or aband- onment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to my best knowledge and belief. WWC Number	
Yield GPM down at Time 7 65 1 hr.	Signed Date	
Temperature of water 53F Depth Artesian Flow Found Was water analysis done? NO By whom Reason for water not suitable for use	(bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my thowledge and belief. WWC Number 1438	
Depth of strata	Signed	04
ORIGINAL & FIRST COPY - WATER RESOURCES DEPTARTMENT SECOND	COPY - CONSTRUCTOR THIRD COPY - CUSTOMER 9809C 10 91WATER RESOURCES SALEM, OREGO	S DEPT