YAMH 55206

WAT	State of Oregon RR WELL REPORT (as required by ORS 537.765) Page 1 o	State Well ID 192925 of 1 Start Card # 1003583 / 003 584
(2)	OWNER: Well No. 2588 Name GRAND CRU LLC Address 2803 ORCHARD AVE City MCMINNVILLE St OR Zip 97128 TYPE OF WORK: NEW WELL	(9) LOCATION OF WELL by legal description: County YAMHILL Lat. 45° 20' 16" Long. 123° 07' 4 Township 3 S Range 4 W WM. Section 1 NW 1/4 SW 1/4 Tax Lot 1000 Lot Block Subdivision Street Address of Well (or nearest Address) 17100 WOODLAND LOOP RD YAMHILL, OR
	DRILL METHOD: ROTARY AIR PROPOSED USE: DOMESTIC	(10) STATIC WATER LEVEL: 27 ft. below land surface. Date 05/29/08 Artesian pressure lb per square in. Date
. ,	BORE HOLE CONSTRUCTION: Special Construction Approval NO Depth of Compl. Well 232 ft Explosives used NO Type Amount HOLE SEAL Diam. From To Material From To Amount 10 0 28 BENTONITE CHIP 0 28 24 SAX 6 28 232	
Backfill Gravel: (6) CASING/LIN	Diam. From To Gauge Material Connection	(12) WELL LOG: Ground elevation Material From To SWL TOP SOIL 0 3 CLAY, TAN 3 19 SANDSTONE, GRAY W/OCC THIN LT GRAY STRAT 19 154
Line	r 4 12 72 SCH40 PLASTIC THREADED 4 92 212 SCH40 PLASTIC THREADED Location of shoe(s) 29, SPLINE-LOC LINER	CLAYSTONE, GRAY W/SILTSTONE STRATS 154 184 CLAYSTONE, GRAY W/OCC LT GRAY SANDSTONE 184 215 CLAYSTONE, GRAY 215 232
	PERFORATIONS/SCREENS: [_] Perf. Method	DAVE PAYSINGER, BLUE WATER DRILLING CO. (503) 868-7878
	72 92 40 4" PS LINER 212 232 40 4" PS LINER	Date started 05/28/08 Completed 05/29/08
(8) 1	WELL TESTS: Minimum testing time is 1 hour	(unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or aband- onment of this well is in compliance with Oregon water supply well construction standards. Materials used and information
•	Test type AIR Draw- Drill stem	reported above are true to my best knowledge and belief. WWC Number
	field GPM down at Time 7.5	(bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported
F	Remperature of water 54F Depth Artesian Flow Found las water analysis done? YES By whom BLUE H2O Reason for water not suitable for use Depth of strata	above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief. WWC Number 1438 Signed Must Again Date 05/30/08

RECEIVED
JUN 2 6 2008
WATER RESOURCES DEPT
SALEM, OREGON