YAMH 55526

ia.		of Oregon REPORT (as required by O	RS 537.765)	Page 1	State Well ID L100552 of 1 Start Card # 1007196
_	City	ARNE GODDIK 18265 SE NECK RD DAYTON F WORK: NEW WELL	Well No. 20	561 Zip 97114	(9) LOCATION OF WELL by legal description: County YAMHILL Lat. ' Long. ' Township 4 S Range 3 W WM. Section 10 SE 1/4 SW 1/4 Tax Lot 1500 Lot Block Subdivision Street Address of Well (or nearest Address) 18265 SE NECK RD DAYTON, OR
(3) DRILL METHOD: CABLE (4) PROPOSED USE: IRRIGATION					(10) STATIC WATER LEVEL:
					65 ft. below land surface. Date 08/24/09 Artesian pressure lb per square in. Date
(5)	Special Explosi		SEAL From To	nt	ft (11) WATER BEARING ZONES:
	Seal nla	acement method POURED/HYD	\D\#\#\		(12) WELL LOG:
(6)	Backfi	ill: from ft to l: from 25 ft to 133	ft Material	3/8" PEA	Ground elevation Material From To SWL TOP SOIL 0 5
	Diaming 6	n. From To Gauge +2 133 .25			CLAY, BROWN
in	er				CLAY, GREEN/GRAY W/SAND 85 91 SEP 2 1 2009
?inal Location of shoe(s) 133					CLAY, GREEN/GRAY W/SOME SAND 96 106 CLAY, GREEN W/SAND AND FINE GRAVEL 106 118 WATER RESOURCES DEP
(7) PERPORATIONS/SCREENS:					CLAY, GREEN/BLUE W/SOME SAND 118 125 SALEM, OREGON CLAY, GRAY 125 133
	[X] Perf. Method TORCH [_] Screens Type Material Material				DAVE PAYSINGER, BLUE WATER DRILLING CO.
				Casing/liner CASING	(503) 868 7878
					Date started 08/17/09
	WPIT MPC	TMC. Winimum tenting time	ig 1 hour		(unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or aband- onment of this well is in compliance with Oregon water supply
	WELL TESTS: Minimum testing time is 1 hour Test type BAILER Draw- Drill stem				well construction standards. Materials used and information reported above are true to my best knowledge and belief. WWC Number
	Yield GP 19		at	Time 1 hr.	Signed Date
	20 30	16 25		2 6	(bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported
	Temperature of water 54P Depth Artesian Flow Found Was water analysis done? NO By whom Reason for water not suitable for use Depth of strata				above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief. WWC Number 1438 Date 08/25/09
OR	IGINAL &	PIRST COPY - WATER RESOUR	RCES DEPTARTMENT	SECOND (OPY - CONSTRUCTOR THIRD COPY - CUSTOMER 9809C 10/91