YAMH 56744

State of Oregon

WATER WELL REPORT (as required by ORS 537.765)

Page 1 of 1

State Well ID L112369 Start Card # 1022101

Name WILLAMETTE HAZELNUT GROWERS Address 14975 NE TANGEN RD	(9) LOCATION OF WELL by legal description: County YAMHILL
(2) TYPE OF WORK: RECONDITION	Tax Lot 2101
(3) DRILL METHOD: ROTARY AIR (4) PROPOSED USE: INDUSTRIAL	(10. STATIC WATER LEVEL: 270
(5) BORE HOLE CONSTRUCTION: Special Construction Approval NO Depth of Compl. Well 376 ft Explosives used NO Type Amount HOLE SEAL Diam. From To Material From To Amount	
Seal placement method	(12) WELL LOG: Ground elevation Material From To SWL
Casing Cannection Casing Casing Connection Liner 4 16 376 SCH40 PLASTIC THREADED Final Location of shoe(s) SPLINE-LOC LINER	RECEIVED BY OWRD
(7) PERFORATIONS/SCREENS: [X] Perf. Method CIRCULAR SAW [_] Screens Type Material	SALEM, OR DAVE PAYSINGER, bluewaterdrilling.com (503) 868 7878 Date started 01/28/14 Completed 01/19/14 (unbonded) Water Well Constructor Certification: I certify that
(8) WELL TESTS: Minimum testing time is 1 hour Test type AIR Draw- Drill stem Yield GPM down at Time	the work I performed on the construction, alteration, or aband- onment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to my best knowledge and belief. WWC Number Signed Date
25 375 1 hr. 25 375 3 Temperature of water 54F Depth Artesian Flow Found Was water analysis done? YES By whom TDS 202PPM Reason for water not suitable for use	(bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
Depth of strata	Signed Jauan 1. Paysun > Date 01/29/.4